General Aviation Modifications, Inc. Installation Procedure, No. IP-98-001

(Rev. B)

Date: March 13, 1998

GAMI	Kit No. GL10
	S/N

GAMIJector * Installation Procedure for Normally Aspirated Lycoming Engines

STC No. SE09445SC

- Remove existing Lycoming fuel injector nozzle assemblies by disconnecting fuel lines at 1. the nozzle assemblies. Remove the nozzle assemblies from the cylinders using a ½ inch deep socket.
- Refer to the number code (1-4,1-6, or1-8 for 4,6, or 8 cylinder engines accordingly) 2. stamped on each nozzle for placement in corresponding cylinder number. (Note: Nozzles are stamped with both number and letter codes). Cylinders are numbered from front to rear with odd numbered cylinders on the right side. Install appropriate GAMIjector® in cylinder and tighten to not more than the torque limit of 60 in. lbs. such that the letter code stamped hex flat is installed within one flat of the bottom of the engine.
- 3. Reconnect and tighten the fuel line to the *GAMIjector*® nozzle.
- Check installation for crimped lines, loose fittings, etc. 4.
- Leak check the GAMIjector® nozzles and associated fuel lines by use of the electric fuel pump, prior to starting the engine. Perform a ground engine run-up and recheck for fuel leaks before flight.
- Clean a flat 1.5" X 2" area on each cylinder rocker arm cover with acetone or isopropyl 6. alcohol. Apply the correct GAMIjector® label to the cleaned area with high temperature RTV silicone, such as Permatex "Ultra Copper" P/N101B or equivalent. Allow to cure, thoroughly, prior to operation of the engine. Remove the fuel line label from its backing. Locate the middle of the tag against the fuel line approximately 5" from the injector nozzle and wrap the correct label (according to its cylinder number identification) around each fuel line going to the appropriate injector, doubling it over onto itself as a tag.
- Check to insure that the GAMIjectors® labels have been installed on the proper cylinder 7. and fuel line and that the GAMIjector® part number in each cylinder corresponds with the part number called out on the labels affixed to its respective cylinder head rocker arm cover and fuel line.

- 8. This STC does not require alteration of the fuel system metered or unmetered fuel pressures or other recalibration of the fuel system. In connection with this STC, no further alteration of the fuel system, other than in compliance with appropriate Lycoming Service Bulletins, airworthiness directives, or compatible STC's is authorized.
- 9. Complete and submit a Form 337 for the aircraft, referencing installation of the General Aviation Modifications, Inc., Kit Number and this STC No. SE09445SC. There is no change in weight and balance.

Instructions for Continued Airworthiness and Periodic Maintenance: GAMI recommends removal and cleaning of the nozzles at normal intervals of 100-200 hours. Nozzles may be soaked in an appropriate solvent such as Gunk carburetor cleaner or Hopi's #9 Gun Solvent, followed by blowing off with an air nozzle. A small hole should be visually clear through the nozzle. Caution: Do not attempt to insert any drill, wire or other article into the nozzle in an attempt to clean the orifices. In the event that a nozzle becomes clogged and requires cleaning and recalibration, it may be returned to GAMI for immediate service.